

In-House Work Order

Signage

SAMPLE REPORT

Room Number 108 - Conference

Existing Condition 29 1/2" wide

Phase Code 8

ADAAG/UFAS Reference 4.13.5

ADAAG/UFAS Figure(s) 24a

Removal Difficulty Q

Barrier Text Clearance width < 32" at doorway

Administrative Method Provide equivalent functions, facilities or services in a location which does not require passage through the noncompliant doorway. Install Directional Sign.

Admin. Method Rough Estimate \$ 82.00

Notes Use adjacent, accessible conference room for meetings with people who are unable to get through narrow door.

**DETAILED
REPORT
OPTION 2
SBS**